

103																				
44,6	433000	433005	433010	433015	433020	433025	433030	433035	433040	433045	433050	433055		433065	433070	433075		433085	433090	433095
59,9	433100	433105	433110	433115	433120	433125	433130	433135	433140	433145	433150	433155	433160	433165	433170	433175	433180	433185	433190	433195

77																				
44,6	433200	433205	433210	433215	433220	433225	433230	433235	433240	433245	433250	433255		433265	433270	433275		433285	433290	433295
59,9	433300	433305	433310	433315	433320	433325	433330	433335	433340	433345	433350	433355	433360	433365	433370	433375	433380	433385	433390	433395

48,8																				
44,6	433400	433405	433410	433415	433420	433425	433430	433435	433440	433445	433450	433455	433460	433465	433470	433475	433480	433485	433490	433495
59,9	433500	433505	433510	433515	433520	433525	433530	433535	433540	433545	433550	433555	433560	433565	433570	433575	433580	433585	433590	433595

44,6

Terminaisons en ¼ de rond

Terminaisons droites

Séparations

48,6 68,6

Jonctions pour colonne mise en angle

44,6	44,6	44,6	44,6
44,6	59,9	44,6	44,6
44,6	44,6	59,9	

Lambris

	433600	433605	433610	433615	433620	433621	433625	433630	433635	433640	433645	433646	433650	433900	433905	433910	433915	433920	433921	433922

59,9

Terminaisons en ¼ de rond

Terminaisons droites

Séparations

Jonctions pour colonne mise en angle

59,9	59,9	59,9	59,9	59,9
59,9	44,6	59,9	44,6	59,9
59,9	59,9	44,6		

	433700	433705	433710	433715	433720	433721	433725	433730	433735	433740	433745	433750	433755	433756	433760	43765				