



44,6	434000	434005	434010	434015	434020	434025	434030	434035	434040	434045	434050	434055		434065	434070	434075		434085	434090	434095		
59,9	434100	434105	434110	434115	434120	434125	434130	434135	434140	434145	434150	434155	434160	434165	434170	434175	434180	434185	434190	434195		



44,6	434200	434205	434210	434215	434220	434225	434230	434235	434240	434245	434250	434255		434265	434270	434275		434285	434290	434295		
59,9	434300	434305	434310	434315	434320	434325	434330	434335	434340	434345	434350	434355	434360	434365	434370	434375	434380	434385	434390	434395		



44,6	434400	434405	434410	434415	434420	434425	434430	434435	434440	434445	434450	434455	434460	434465	434470	434475	434480	434485	434490	434495		
59,9	434500	434505	434510	434515	434520	434525	434530	434535	434540	434545	434550	434555	434560	434565	434570	434575	434580	434585	434590	434595		

Terminaisons en ¼ de rond Terminaisons droites

44,6

48,6 68,6

Jonctions pour colonne mise en angle

44,6	44,6	44,6	44,6
44,6	59,9	44,6	44,6
44,6	44,6	59,9	

Lambris

Terminaisons en ¼ de rond Terminaisons droites Séparations

59,9

Jonctions pour colonne mise en angle

59,9	59,9	59,9	59,9	59,9
59,9	44,6	59,9	44,6	59,9
59,9	59,9	44,6		

	434700	434705	434710	434715	434720	434721	434725	434730	434735	434740	434745	434750	434755	434756	434760	434765						